APPENDIX C:
COMBINED TEST RESULTS TABLE

Robert's New Type.

NASA - JSC
Orbiter Tile Impact Testing
SwRI Project No. 06-7503-005

Test No. TuFI - 2

Date: 12/10/98
Time: 4:00
Conditions: Rainy 46°F
Staff: _____

Target Description:

Serial No. Robert's Tile
Obliquity (deg.): 60°

Projectile Description:

Projectile Dimensions: 1" X 1" X 1"
Projectile Weight (g): _____
Sabot Weight (g): _____
Total Weight (g): .6

Gun Pressure (psi): P1: 600, P2: 180, P3: 600

Velocity Measurement:

Measurement	Time (us)		Velocity (fps)
1	_____		_____
2	_____		_____
		Ave.	1575

Tile Damage Assessment:

Crater (Y/N): Length:_____ Width:_____ Depth:_____

Volume:_____ (Weight of Sand _____ x Sand Density ____)

Tile Cracking (Y/N – Describe):
Coating Delamination 2.5" X 1.5"

Comments:
- Special New Tile Design
- Intended Velocity 1600
- Projectile Slightly Broken Up - OK
- Good Test

NASA - JSC
Orbiter Tile Impact Testing
SwRI Project No. 06-7503-005

Test No. TUFI - 1

Date: 12/11/98
Time: 10:50
Conditions: 43° F
Staff: _____

Target Description:

Serial No. TUFI-1
Obliquity (deg.): ~~60~~ 50°
→ 40°

Projectile Description:

Projectile Dimensions: 1" x 1" x 3"
Projectile Weight (g): 1.22
Sabot Weight (g): _____
Total Weight (g): _____

Gun Pressure (psi): P1: 600, P2: 200, P3: 600

Velocity Measurement:

Measurement	Time (us)	Velocity (fps)
1	_____	_____
2	_____	_____
Ave.	_____	_____ guess 1432 fps

Tile Damage Assessment:

Crater (Y/N) Length: 1.5" dia Width: _____ Depth: 1/8"

Volume: _____ (Weight of Sand _____ x Sand Density ____)

Tile Cracking (Y/N – Describe):

_____

_____

Comments:

- No Impact / No Velocity
- Probably Broken Projectile like test 60

NASA - JSC
Orbiter Tile Impact Testing
SwRI Project No. 06-7503-005

Test No. New 104

Date: 1/5/98
Time: 3:45
Conditions: Sunny 55°
Staff: DLG

Target Description:

Serial No. FIT Tile
Obliquity (deg.): 30°

Projectile Description:

Projectile Dimensions: 3/8" X 3.0"
Projectile Weight (g): .23
Sabot Weight (g): _____
Total Weight (g): _____

Gun Pressure (psi): P1: 600, P2: 110, P3: 600

Velocity Measurement:

Measurement	Time (us)		Velocity (fps)
1	_____		_____
2	_____		_____
		Ave.	1250

Tile Damage Assessment:

Crater (Y/N): Length:_____ Width:_____ Depth:_____

Volume:_____ (Weight of Sand _____ x Sand Density ____)

Tile Cracking (Y/N – Describe):

≈ 1.01" dia X 0.9" deep

Comments:

- Same FIT Tile as Test No. New99B - new spot
- Good Test - Velocity (+50 fps)
- Projectile slightly broken up

NASA - JSC
Orbiter Tile Impact Testing
SwRI Project No. 06-7503-005

Test No. New 103

Date: 1/5/99
Time: 5:01
Conditions: Sunny 55°
Staff: DLG

Target Description:

Serial No. Flt Tile
Obliquity (deg.): 60°

Projectile Description:

Projectile Dimensions: 3/8" dia x 3.0" Lgth
Projectile Weight (g): .23g
Sabot Weight (g): _____
Total Weight (g): _____

Gun Pressure (psi): P1: 600, P2: 60, P3: 600

Velocity Measurement:

Measurement	Time (us)	Velocity (fps)
1	_____	_____
2	_____	_____
	Ave.	1071

Tile Damage Assessment:

Crater (Y/N): Length: 1.5" Width: 1.0" Depth: 0.5"

Volume: _____ (Weight of Sand _____ x Sand Density ____)

Tile Cracking (Y/N – Describe):

Comments:

Air → PT 0.1

- Pretest Cracks
- Good Test Velocity (+46 fps)
- Projectile Slightly Broken up - Back 1/4

NASA - JSC
Orbiter Tile Impact Testing
SwRI Project No. 06-7503-005

Test No. New 101 B ← used for both 101 and 102

Date: 1/5/98
Time: 4:50
Conditions: Sunny 55°
Staff: DLG

Target Description:

Serial No. Eg Tile
Obliquity (deg.): 60°

Projectile Description:

Projectile Dimensions: 3/8" dia x 3.0" Length
Projectile Weight (g): .23 g
Sabot Weight (g): _____
Total Weight (g): _____

Gun Pressure (psi): P1: 600, P2: 85, P3: 600

Velocity Measurement:

Measurement	Time (us)		Velocity (fps)
1	_____		_____
2	_____		_____
		Ave.	1319

Tile Damage Assessment:

Crater (Y/N): Length: 1.85" Width: 1.08" Depth: 0.5"

Volume: _____ (Weight of Sand _____ x Sand Density ____)

Tile Cracking (Y/N – Describe):

Comments:

- Good Test - Velocity (+191 fps)

NASA - JSC
Orbiter Tile Impact Testing
SwRI Project No. 06-7503-005

Test No. New 101A

Date: 1/5/99
Time: 4:40
Conditions: Sunny 55°
Staff: DLG

Target Description:

Serial No. Eng Tile
Obliquity (deg.): 60°

Projectile Description:

Projectile Dimensions: 3/8" dia x 3.0"
Projectile Weight (g): .23g
Sabot Weight (g): _____
Total Weight (g): _____

Gun Pressure (psi): P1: 600, P2: 400, P3: 600

Velocity Measurement:

Measurement	Time (us)	Velocity (fps)
1	_____	_____
2	_____	_____
Ave.		1400

Tile Damage Assessment:

Crater (Y/N): Length: 1.6" Width: 0.8" Depth: 0.58

Volume: _____ (Weight of Sand _____ x Sand Density _____)

Tile Cracking (Y/N – Describe):

Comments:

New Eng Tile
Good Test - Velocity (+104 fps)
Too Fast

NASA - JSC
Orbiter Tile Impact Testing
SwRI Project No. 06-7503-005

Test No. New 101

Date: 1/5/98
Time: 4:30
Conditions: Sunny 55°
Staff: DLG

Target Description:

Serial No. FIT Tile
Obliquity (deg.): 60°

Projectile Description:

Projectile Dimensions: 3/8" dia X 3.0" Length
Projectile Weight (g): .23g
Sabot Weight (g): _____
Total Weight (g): _____

Gun Pressure (psi): P1: 600, P2: 110, P3: 600

Velocity Measurement:

Measurement	Time (us)		Velocity (fps)
1	_____		_____
2	_____		_____
		Ave.	1567

Tile Damage Assessment:

Crater (Y/N): Length: 2.09" Width: .87" Depth: 0.58"

Volume: _____ (Weight of Sand _____ x Sand Density _____)

Tile Cracking (Y/N – Describe):

Comments:

- Some FIT Tile as Test # New 98A - New Spot
- Projectile Broke into Pieces
- Velocity (+ 361 fps) - Too Fast
- Big Gouge

NASA - JSC
Orbiter Tile Impact Testing
SwRI Project No. 06-7503-005

Test No. 97 (~~Abbott~~) ← This will be used as Test #100 in the Matrix

Date: 12/9/98
Time: 9:15
Conditions: Cloudy 51°F
Staff: DLG, LB, DJG

Target Description:

Serial No. Eng Tile
Obliquity (deg.): 60°

Projectile Description:

Projectile Dimensions: 3/8" dia x 1.0" Length
Projectile Weight (g): .089
Sabot Weight (g): —
Total Weight (g): .08

Gun Pressure (psi): P1: 600, P2: 50, P3: 600

Velocity Measurement:

Measurement	Time (us)	Velocity (fps)
1		
2		
	Ave.	929

Tile Damage Assessment:

Crater (Y/(N)) Length:_____ Width:_____ Depth:_____

Volume:_____ (Weight of Sand _____ x Sand Density ____)

Tile Cracking (Y/N – Describe):

Comments:

- 10" Standoff from Barrell to Impact site
- New Eng. Tile – NO cracking
- No Damage
- Intended Velocity 1009 (-80 fps)



Test No. 51B



Test No. 52B


TILE PENETRATION TESTS
TILE PENETRATION TESTS
TILE PENETRATION TESTS
TILE PENETRATION TESTS
TILE PENETRATION TESTS
TILE PENETRATION TESTS
TILE PENETRATION TESTS

Test No. 53



Test No. 54



Test No. 55


NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS

Test No. 56



Test No. 57A


NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS

Test No. 58


NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS

Test No. 59A


NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS

Test No. 60



Test No. 81



Test No. 82


NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS

Test No. 83


NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS

Test No. 84B


NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS

Test No. 85


NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS

Test No. 86



Test No. 89



Test No. 90B


NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS

Test No. 91


NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS

Test No. 92


NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS

Test No. 93


NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS
NASA - TILE PENETRATION TESTS

Test No. 94A

Test No. 97



Test No. 98A

Test No. 99B



Test No. 100



Test No. 101B



Test No. 103



Test No. 104



Test No. Tufi-2